



# ASSEMBLY INSTRUCTION





# ASSEMBLY INSTRUCTION




① x4  
M6\*20




② x4




③ x1




④ x2




Ⓐ x01



Ⓑ x01



Ⓒ x01



Ⓓ x01



Ⓔ x01



Ⓕ x01



Ⓖ x02




Ⓗ x03




Ⓘ x01


Step 1




Step 2



Step 3






① x4  
M6\*20




② x4




③ x1




④ x2




Ⓐ x01



Ⓑ x01



Ⓒ x01



Ⓓ x01



Ⓔ x01



Ⓕ x01



Ⓖ x02




Ⓗ x03




Ⓘ x01

# ASSEMBLY INSTRUCTION


Step 4




Step 5




Step 6




Step 7





# ASSEMBLY INSTRUCTION



① x16  
M6\*20



② x16




③ x16




④ x01




⑤ x02



① x01




② x04




③ x01


Step 1




Step 2




Step 3





# ASSEMBLY INSTRUCTION



① x18  
M6\*20



② x18




③ x18



④ x01



⑤ x02




① A x01




② B x02



③ C x01




④ D x02




⑤ E x01


Step 1



Step 2



Step 3



Step 4

